

CDL Program Overview August 17, 2020

Orientation and Permit Preparation

- 1. Door code = 7822#
- 2. WiFi access, PeasleeGuest, password = wireless
- 3. Review course syllabus
- 4. Complete Truckers Against Trafficking training and print certificate at this link.
- 5. Complete permit study guides sent to your email address. Open study guide on one screen, or your phone, and go to this link to look up the answers. GO TO THE BOTTOM OF THE FORM AND CLICK "SUBMIT" WHEN YOU TAKE A BREAK OR BEFORE CLOSING THE STUDY GUIDE. On the General Knowledge section, complete a practice test after each 100 questions.
- 6. Complete practice tests (complete three examinations for each section; General Knowledge, Airbrakes, and Combination Vehicle, with a minimum score of 85% at this link.
- 7. When you have completed the permit preparation, call the Topeka CDL Driver Testing Center, 3907 SW Burlingame Road, Topeka, KS 66609, 785-940-1309 to make an appointment for your permit exam. <u>TELL THEM YOU ARE A PEASLEE TECH STUDENT.</u> Be sure to bring your Truckers Against Trafficking certificate to get your permit.
- 8. When you have successfully completed the permit examination, call LMH Business Health Center, 325 Maine St., 785-505-3114 and schedule your DOT physical.
- 9. Upon attainment of your CDL Permit and DOT Physical, please provide copies to the administrative office of Peaslee Tech.

Skills Examinations Preparation

- 1. Register and complete Trucking Truth *The High Road* (https://www.truckingtruth.com/cdl-training-program/) online training.
- 2. Safety/Pre-trip Inspection. Demonstrate competency in all aspects of the inspection.
- 3. Backing test. Demonstrate competency in all backing maneuvers.
- 4. Road test. Demonstrate competency in all aspects of the road test.
- 5. Upon successful completion of in-class final examination, a license examination will be scheduled.
- 6. To take your exam, you need the following documents (YOU MUST BRING ALL):
 - Driver's license, permit, DOT physical card, and Truckers Against Trafficking certificate